TOSHIBA CMOS Digital Integrated Circuit   Silicon Monolithic

JTC83230-0014S

JTC83230-0014S: Single-Chip CMOS LSI for Calculators with Printers
(applicable printer heads: PTMFL 63 manufactured by ALPS)

The JTC83230-0014S LSI is a single-chip CMOS LSI for use in calculators with printers.
It integrates I/O logic circuits necessary to configure a calculator with 10-digit display, two-memory function, serial printer used to print calculation results, oscillator, and LCD drivers.

Features

Operational Features

- Print: 11 digits of data. (including decimal point.) 1 digit of minus sign, 2 digits of operational symbol.
    1-color printing (black).
- Display: 10 digits of data. (including punctuation in each digit.)
    1 digit of floating minus sign, memory load, error symbol, grand total memory load, 3 digits of commas.
- Decimal output: Decimal set lock key controls output format. Fixed decimal setting ("0", "1", "2", "3", "4", "6"), full floating decimal, and ADD mode.
- Key-input buffer: 12 words
- Operation methods: Addition and subtraction: By ARITHMETIC operation
    Multiplication and division: By algebraic operation
- Function: Four function, repeat multiplication and division, mixed calculation, square calculation, percentage calculation, percent discount and add-on calculation, memory calculation, delta percent calculation, add-mode calculation, mark-up/down calculation, total calculation, constant calculation, tax calculation
    Two-key rollover
- Leading zero suppression

Protection

(1)   In the overflow condition, all key except "C", "C/CE", "CE", "Feed", "→" key are inoperative.
(2)   Key chatter protection.

Auto-Clear at Power On

Auto-clear functions by connecting a capacitor to the RESET pin.

TOSHIBA

System Block Diagram

JTC83230-0014S

LCD 10 digits

SEG11, SEG10, SEG9, SEG8, SEG7, SEG6, SEG5, SEG4, SEG3, SEG2, SEG1, SEG0, R73, R72, R71, R70, R63, R62, R61, R60, R53, R52, R51, R50

SEG12, SEG13, SEG14, SEG15, SEG16, SEG17, SEG18, SEG19, SEG20, SEG21, SEG22, SEG23, SEG24, SEG25, SEG26, SEG27

R43, R42, R41, R40, R92, R91, R90, VDD, R83, R82, R81, R80, KO3, KO2, KO1, KO0

SEG28, SEG29, SEG30, SEG31, COM1, COM2, COM3, COM4, N.C., VLC, P10, P11, P12, P13, VSS, P20, P21, P22, P23, TEST, XIN, XOUT, BRESET, BHOLD

VLC

VDD

VDD

Vp

LOCK KEY

TOUCH KEY

PTMFL-63

M

2

## Connection of LCD

Segment

Common

Key Connection

Touch Key

Lock Key

Touch Key Select

ON Key

Specification of Calculator

Operation Specifications

(1) Operations depending on key types and modes

- Touch key

Key Name	CAL Mode		TAX Set Mode (SETI/II key is ON)	
Mode Switch	Touch Key Mode	Lock Key Mode	Touch Key Mode	Lock Key Mode
C	Operates as clear key	Operates as clear key	Clears input data	Clears input data
CE	Operates as clear entry key	Operates as clear entry key	Clears input data	Clears input data
C/CE	Operates as clear or clear entry key	Operates as clear or clear entry key	Clears input data	Clears input data
Numeral	Numeral Key-inputs numerals	Numeral Key-inputs numerals	Inputs numerals	Inputs numerals
OFF	Operates as off key	—	Unused	Unused
.	Key-inputs decimal points	Key-inputs decimal points	Key-inputs decimal points	Key-inputs decimal points
*, ◊	Operates as total or sub-total key	Operates as total or sub-total key	Unused	Unused
+, − ×, ÷	Operates as four-function key	Operates as four-function key	Unused	Unused
=	Operates as = key	Operates as = key	Unused	Unused
P/NP	Switches print or non-print	—	Unused	Unused
RND	Switches round-off and round-up	—	Unused	Unused
DEC	Switches decimal points	—	Unused	Unused
%	Operates as % key	Operates as % key	Unused	Unused
Δ%	Operates as delta percentage calculation key	Operates as delta percentage calculation key	Unused	Unused
MU/D	Operates as mark-up/down key	Operates as mark-up/down key	Unused	Unused
IC/AVE	Operates as item count key or average key	Operates as item count key or average key	Unused	Unused
#/P	Operates as non-add-print key for left-justified printing	Operates as non-add-print key for left-justified printing	Unused	Unused
→	Operates as right-shift key	Operates as right-shift key	Operates as right-shift key	Operates as right-shift key
+/−	Operates as sign change key	Operates as sign change key	Unused	Unused
MI*, MII* MI◊, MII◊, MI−, MII−, MI+, MII+	Operates as memory function key	Operates as memory function key	Unused	Unused
−TAXI/II	Operates as −TAXI/II key	Operates as −TAXI/II key	Unused	Unused
+TAXI/II	Operates as +TAXI/II key	Operates as +TAXI/II key	Unused	Unused
Σ	Operates as Σ key	—	Unused	Unused
IC MOD	Operates as IC-mode key	—	Unused	Unused

Key Name	CAL Mode		TAX Set Mode (SETI/II key is ON)	
Mode Switch	Touch Key Mode	Lock Key Mode	Touch Key Mode	Lock Key Mode
GT MOD	Operates as GT-mode or non-GT mode key	—	Unused	Unused
GT$^{\Diamond}_{*}$	Operates as GT key	Operates as GT key	Unused	Unused
EXC	Operates as EXC key	Operates as EXC key	Unused	Unused
$\sqrt{}$	Operates as $\sqrt{}$ key	Operates as $\sqrt{}$ key	Unused	Unused

- Lock key

Key Name	CAL Mode		TAX Set Mode (SETI/II key is ON)	
Mode Switch	Touch Key Mode	Lock Key Mode	Touch Key Mode	Lock Key Mode
0, 1, 2, 3, 4, 6, A, AII	—	Switches decimal points	Unused	Unused
CUT, UP	—	Switches round-off and round-up	Unused	Unused
IC±, IC+	—	Operates as IC±/IC+ key	Unused	Unused
Σ	—	Operates as Σ key	Unused	Unused
GT	—	Switches GT-mode or non-GT mode	Unused	Unused
FEED	Operates as paper feed key	Operates as paper feed key	Operates as paper feed key	Operates as paper feed key
P/$\overline{\text{NP}}$	—	Switches print or non-print	Unused	Unused
$\overline{\text{T}}$/L (Note 1)	Selects lock key mode or touch key mode.			
2 TAX (Note 1)	Selects single tax mode or double tax mode.			
2 M (Note 1)	Selects single memory mode or double memory mode.			

Note 1: Can switch modes only with the reset key.

(2) Explanation of function

[0~9]...................... Keys in numbers from 0 to 9, 00, and 000. If the number of displays digits exceeds
[00, 000]　　　　　 10 or 12 key entry is invalid.

[·].......................... If this key is pressed after a key operation except data entry, the displays is
cleared and entry of [·] is stored in memory. The decimal point is shifted for
subsequent data entry. If the [·] key is pressed during data entry, displays does
not change.

[+, −]...................... Add or subtract operation data and displays the result. The decimal point is
floating except when A mode is specified. Addition or subtraction can be performed
repeatedly.
If these key are pressed in multiplication/division mode or in constant calculation
mode, add or subtract displays data to addition/subtraction registers, then displays
the result. At this time, in the operation mode multiplicand or divisor do not
change.
These keys increment or decrement the item counter. In the following operation
mode, the operations are executed, and the results are printed and displayed. At
that time, addition or subtraction using the addition/subtraction register is not
executed.

　　1)　percent discount/add-on calculation
　　　　$a \times b\% + ...a + (ab/100)$
　　　　　　$c\% + ...a + (ac/100)$
　　　　$a \times b\% − .....a − (ab/100)$
　　　　　　$c\% − ......a − (ac/100)$

　　Percent discount/add-on with constants are calculated as above.

[◊].......................... Prints and displays the intermediate result in addition/subtraction register. In
item count mode, prints the contents of the item counter before the calculation
result printing.
Contents of data register or stored arithmetic instruction are not changed.

[*].......................... Prints and displays the result in addition/subtraction register. Automatically feeds
paper one line. In item count mode, the contents of the item counter are printed
before the calculation result printing.
After this key operation, the contents of the addition/subtraction register are
cleared. The contents of the item counter are cleared at the first
addition/subtraction in next step. The contents of the data register or stored
arithmetic instruction are not changed. When GT mode is specified, the result of
addition/subtraction is added to the GT memory.

⎡MI+, MII+⎤.......... If the arithmetic instruction is not stored or if the mode is constant calculation
⎣MI−, MII−⎦　　　 mode, first prints the displays contents after rounding to the specified number of
decimal places, performs addition/subtraction using the data in memory, then
stores the result in memory. If the multiplication/division instruction is stored,
executes the arithmetic instruction, rounds the result to the specified number of
decimal places, prints and displays the result, adds/subtracts with the data in
memory, then stores the result to memory.
At that time, the multiplicand or divisor is stored together with the mode, constant
calculation mode. When this key is pressed immediately after the [×] or [MI+, MII+,
MI−, MII−] key, operation is the same as that for the [=] key; that is, adds/subtracts
using data in memory. This key operation increments or decrements the item
counter for memory.

[MI◊, MII◊]............ Prints or displays the intermediate result of memory calculation. In item count
mode, prints the contents of the item counter for memory before the calculation
result printing. Contents of the data register or stored arithmetic instruction are
not changed.

[MI*, MII*] .... Prints and displays the result of memory calculation and automatically feeds paper one line. In item count mode, prints the contents of the item counter for memory before the calculation result printing. After the [MI*, MII*] key operation, the contents of memory and the contents of the item counter for memory are cleared. Contents of the data register or stored arithmetic instruction are not changed.

[×, ÷] .... If the multiplication or division instruction is stored in memory, prints the operators, performs the operations and displays the results while simultaneously storing a new arithmetic instruction in memory. The decimal point for the result is floating. If the [×] or [÷] key is pressed in constant calculation mode, prints the displayed numeric value without performing an operation and stores a new multiplication/division instruction in memory.

[=] .... Executes a stored multiplication/division instruction, rounds the result to the specified number of decimal places, prints and displays the result, then automatically feeds the paper one line. Stores the multiplicand or divisor together with constant calculation mode in memory. If an instruction is not stored in memory, no operation is performed and the previous state is held. Pressing the [=] key immediately after the [×] or [÷] key performs the following operation.

$a \times = $.......$aa$
$a \div = $.......$1$

[%] .... If an arithmetic instruction is stored in memory, performs percentage calculation, rounds the result to the specified number of decimal places, prints and displays the result. Stores the multiplicand/divisor together with constant calculation mode in memory. If a percentage calculation for multiplication is performed, percent discount/add-on calculation can be done by using the [+] or [–] key. At that time, addition/subtraction using the addition/subtraction register is not performed. If an arithmetic instruction is not stored in memory, no operation is performed and the previous state is held. Pressing the [%] key immediately after the [×] or [÷] key performs the following operation.

$a \times \% = $...$aa/100$
$a \div \% = $...$100$

% key operation example: percent discount/add-on calculation

$a \times b\%$....$ab/100$
$+$.............$a + (ab/100)$
$c\%$ ....$ac/100$
$+$.............$a + (ac/100)$
$a \times b\%$....$ab/100$
$-$.............$a - (ab/100)$
$c\%$ ....$ac/100$
$-$.............$a - (ac/100)$

[MU/D] .... If a multiplication/division instruction is stored in memory, cancels the data. The decimal point for the result is floating.

MU/D key operation example:

a MU/D $b = $ .... $a/(1 - (b/100)) - a$ (prints profit)
　　　　　　　　　　　$a/(1 - (b/100))$ (mark-up)
　　　　$c = $................. $a/(1 - (c/100)) - a$ (prints profit)
　　　　　　　　　　　$a/(1 - (c/100))$ (mark-up)
a MU/D b +/– $ = $ .... $a/(1 + (b/100)) - a$ (prints profit)
　　　　　　　　　　　$a/(1 + (b/100))$ (mark-down)
　　　c +/– $ = $........... $a/(1 + (c/100)) - a$ (prints profit)
　　　　　　　　　　　$a/(1 + (c/100))$ (mark-down)

[Δ%] .... If a multiplication/division instruction is memorized, cancels the data.

Δ% key operation example:

aΔ% b = ... b – a		
	(b – a)/│a│	(prints difference)
c = ... c – a		(change delta percent)
	(c – a)/│a│	(prints difference)
aΔ% b +/– = ... –(b + a)		(change delta percent)
	–(b + a)/│a│	(prints difference)
c +/– = ... –(c + a)		(change delta percent)
	–(c + a)/│a│	(prints difference)

[+/–] .... Inverts sign of the displayed number at key entry.

[→] .... Shifts the contents of the displays to the right by one digit at key entry. For an estimation calculation error, cancels the error.

[GT$^\Diamond_*$] .... Calls the contents of GT memory. If the key is pressed once, calls the contents of GT memory, but does not change current state. If the key is pressed twice, calls the contents of GT memory and clears them.

[C] .... Cancels all arithmetic instructions and errors, clears the contents of all the registers except the memory register, and prints 0.C.

[CE] .... If pressed at key entry, clears only the contents of the displays; does not change the stored arithmetic instruction or the contents of the data register. Invalid if pressed after one of the following keys: [C] [×] [÷] [+] [–] [=] [%] [Δ%] [MI+, MII+] [MI–, MII–] [MI◊, MII◊] [MI∗, MII∗] [MU/D] [IC/AVE].
The result of pressing the [CE] key after the [#/P] key depends on the state before the keys were pressed.

[IC+] .... Selects item count mode.
[IC±]   IC+ .... Counts up by the [+] or [–] key.
                             IC± .... Counts up by the [+] key, down by the [–] key.

[Σ] .... If an operation is performed by the [=] or [%] key in auto accumulation calculation mode, adds the operation result to the addition/subtraction register and increments the item counter.

[C/CE] .... If pressed at key entry, operates same as the [CE] key.
If pressed after one of the following keys, operates same as the [C] key: [C/CE] [×] [÷] [+] [–] [=] [%] [Δ%] [MI+, MII+] [MI–, MII–] [MI◊, MII◊] [MI∗, MII∗] [MU/D] [IC/AVE].
The result of pressing the [C/CE] key after the [+/–] or the [#/P] key depends on the state before the keys were pressed.

[#/P] .... If pressed after the numerical key entry, prints the contents of the key entry data register together with the # symbol, but does not change the current state. If the key is pressed after a key except the numerical keys or [+/–] key, does not change the contents of the displays or the current state. If the key is pressed in clock mode, automatically prints the displayed date and time.

$\begin{bmatrix} +\text{TAXI/II} \\ -\text{TAXI/II} \end{bmatrix}$ .... Calculate included tax operation or excluded tax operation. But, only prints and does not express the tax. Prints or displays the result-value. (result-value adjusts decimal-point (TAB) setting.) Feeds the paper one line after prints.

TAXI key operation example: (TAX = 3%)

    a [+TAXI].......... a (3/100)   (prints TAX)

                   a + (a (3/100))   (included TAX)

    a [−TAXII]......... a/(1 + 3/100) − a (prints TAX)

                   a/(1 + 3/100)   (excluded TAX)

If pressed at key entry after number key entry, calculate the tax as a result of calculation.

When multiplication/division instruction is stored in memory.

[P/NP].................. Switches between PRINT and NON-PRINT mode. At reset, NON-PRINT mode is set. Switches mode in each time when the [P/NP] key is pressed: P → NP → P → NP. In PRINT mode, displays "print mode". Valid only when the [$\overline{\text{T}}$/L] lock key is off.

[RND] .... Switches between round-up, round-off and half-adjust. At reset, half-adjust is set. Switches the mode in each time when the [RND] key is pressed: 5/4 → ↓ → ↑ → 5/4 → ↓ → ↑. Displays round-up/round-off. Valid only when the [$\overline{\text{T}}$/L] lock key is off.

[EXC].................... If an multiplication or division instruction is not stored in memory, it is invalid. Constant calculation of multiplication or division instruction exchange for the value of displays, and displays it.

[GT MOD] .... Exchange GT-mode. (initial setting isn't support GT-mode.)
GT mode cycles not-support and support. And displays GT-mode flag.
Only touch key mode is valid.

[IC MOD].............. Exchange IC-mode. (initial setting isn't support IC-mode.)
IC-mode cycles not-support, IC+ and IC±-mode. And displays IC-mode flag. Any touch key mode is valid.

[$\sqrt{}$]...................... Operates root-instruction and displays result-value with prints. (result-value adjusts decimal-point (TAB) setting.)
After prints feeds the paper one line. If the value is minus, change to the plus value and operate root-instruction. Then produce an estimate calculation-error. But keep the arithmetic instruction and date-register.

[IC/AVE].............. Prints or displays the item counter, when IC/AVE key continuously pressed twice just after pressed [∗] key and [◊] key,

After first, prints or displays the item counter.

The second, the calculation of the mean number are executed, prints or displays the operation result.

After calculation of the mean number, item counter are cleared.

Example

a (+)
b (+)
c (+)   Addition to total
d (+) ⟶ addition/subtract
e (+)   register
f (+)
g (+)

(∗)   ⟶ Displays or prints addition/ subtract register.

(IC/AVE) ⟶ Displays the item counter

(IC/AVE) ⟶ Displays or prints $(a + b + c + d + e + f + g)/7$

Then even if IC-value is a negative, the calculation of the mean number.

Example

a (−)
b (−)   Addition to total
c (+) ⟶ addition/subtract
d (−)   register

(∗)   ⟶ Displays or prints addition/ subtract register.

(IC/AVE) ⟶ Displays the item counter

(IC/AVE) ⟶ Displays or prints

$(-a - b + c - d)/\left|\,4\,\right|$ (IC+)

$(-a - b + c - d)/\left|\,-2\,\right|$ (IC±)

[DEC].................... Switches the decimal point. At reset, floating point (F) is set. Switches the mode in each time when the [DEC] key is pressed as follows: $F \to 0 \to 1 \to 2 \to 3 \to 4 \to 6 \to A \to AII \to F \to 0 \to 1$. Displays the specified decimal point or add mode. Valid only when the [$\overline{\text{T}}$/L] lock key is off.

(3) Explanation of lock keys

[0, 1, 2, 3].............. Sets the specified decimal point. If no specification, floating is set.

[4, 6, A, AII]   When processing floating point data, the operation result is zero-shifted. When A mode is specified, key-entered data are multiplied by 1/100 only when the key-entered numerical value is used for addition/subtraction or memory addition/subtraction. If the [·] key is pressed during data entry, A mode is invalid. The operation result is treated the same as the specified decimal point, 2. When AII mode is specified, key-entered data are multiplied by 1/100 only when the key-entered numerical value is used for multiplication/division by [=] key. If the [·] key is pressed during data entry, AII mode is invalid. The operation result is treated the same as the specified decimal point, 2.

[CUT, UP] .... Rounds-off in CUT mode; rounds-up in UP mode; when no specification is made, half-adjusts. When a decimal point is specified, the digit (s) in the subsequent decimal place is (are) half-adjusted, rounded-off, or rounded-up (??). If floating point is specified, the value of the least significant digits which cannot be displayed is rounded off.

[P/$\overline{\text{NP}}$] .... Switches between print and non print mode. When [P/$\overline{\text{NP}}$] lock key is off, disables all printing except [PF] or [#/P] key.

When mode changes from non-print to print, feeds the paper one line.

[IC+]...................... Selects item count mode.

[IC±]   IC+.........Counts up by the [+] or [−] key.

                             IC±.........Counts up by the [+] key, down by the [−] key.

[Σ] .... If an operation is performed by the [=] or [%] key in auto accumulation calculation mode, adds the operation result to the addition/subtraction register and increments the item counter.

[GT] .... In grand total mode, adds the total register to the GT register by the [∗] key.

[$\overline{\text{T}}$/L] .... When the [$\overline{\text{T}}$/L] lock key is off, the [P/NP], [Σ], [GT MOD], [IC MOD], [RND], and [DEC] keys are valid. When the [$\overline{\text{T}}$/L] key is on, the [NP], [Σ], [GT], [IC+], [IC±], [CUT], [UP], and [0, 1, 2, 3, 4, 6, A, AII] lock keys are valid.

$\begin{bmatrix} \text{SETI} \\ \text{SETII} \end{bmatrix}$ .... When the [SETI/SETII] lock key is on, prints and express the stored tax rate. When the [SETI/SETII] lock key is off, store the expression data to the new tax rate. The result of tax rate is only floating-point, and not concent the decimal-point at this function.

[FEED] .... Feed paper.

[TMR] .... When the [TMR] lock key is on, auto power-off functions. (after approx. 6 minutes.)

[2 TAX] .... Switches between single tax and double tax mode. When the [2 TAX] lock key is on, one tax rate can be set. (SETII and TAXII will be disabled.) When the [2 TAX] lock key is off, two tax rates can be set.

[2 M] Selects single memory or double memory mode. When the [2 M] lock key is on, one memory can be used. (MII will be disabled.) When the [2 M] lock key is off, two memories can be used.

(4) ON, OFF key

[ON] .... If pressed in HOLD mode, cancels HOLD. At that time, cancels all arithmetic instructions and errors. The contents of the memory register and the TAX RATE before HOLD mode are retained; all other registers are cleared. While the [ON] key is pressed, the [OFF] key is invalid.

[OFF] .... Forcibly enters HOLD mode (CPU sleep mode).

Operation Example

TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M	Touch	Print	Display
F	4/5	OFF	OFF	OFF	CAL	OFF	OFF	POWER ON		
									<PF>	
									*	
									<PF>	0.
								1+	1· +	1.
								2−	2· −	-1.
								◊	-1· ◊	-1.
								*	-1· *	
									<PF>	-1.
								IC/AVE	2·	2.
F	4/5	IC+	OFF	OFF	CAL	OFF	OFF	IC/AVE	-0·5 ÷ *	-0.5
								IC/AVE	0·	0.
								1+	1· +	1.
								2−	2· −	-1.
								◊	002	
									-1· ◊	-1.
								IC/AVE	2·	2.
								IC/AVE	-0·5 ÷ *	-0.5
								IC/AVE	2·	2.
								*	002	
									-1· *	
									<PF>	-1.
								IC/AVE	2·	2.
								IC/AVE	-0·5 ÷ *	-0.5
								IC/AVE	0·	0.
F	4/5	OFF	OFF	OFF	CAL	OFF	OFF	3×	3· ×	3.
								4÷	4· ÷	12.
								=	4· =	
									3· *	
									<PF>	3.
								5×	5· ×	5.
								6%	6· %	
									0·3 *	
									<PF>	0.3
								+	5·3 + %	
									<PF>	5.3
								2÷	2· ÷	2.
								3%	3· %	
									66·66666666 *	
									<PF>	66.66666666
								2 MU/D	2· M	2.
								3=	3· %	

Note 2: <PF> ....Paper feed

Key								Touch	Print		Display
TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M				
									0.06185567	◊ *	
									2.06185567	*	
									<PF>		2.06185567
								2Δ%	2·	◊	2.
								3=	3·	=	
									1·	◊ *	
									50·	◊ %	
									<PF>		50.
F	4/5	OFF	Σ	OFF	CAL	OFF	OFF	3×	3·	×	3.
								4÷	4·	÷	12.
								=	4·	=	
									3·	+	
									<PF>		3.
								5×	5·	×	5.
								6%	6·	%	
									0·3	+	
									<PF>		0.3
								+	5·3	+ %	5.3
								2÷	2·	÷	2.
								3%	3·	%	
									66·66666666	+	
									<PF>		66.66666666
								2 MU/D	2·	M	2.
								3=	3·	%	
									0.06185567	◊ *	
									2.06185567	+	
									<PF>		2.06185567
								2Δ%	2·	◊	2.
								3=	3·	=	
									1·	◊ *	
									50·	+	
									<PF>		50.
								*	122·0285223	*	
									<PF>		122.0285223
F	4/5	OFF	Σ	GT	CAL	OFF	OFF	2+	2·	+	2.
								3+	3·	+	5.
								*	5·	* +	
									<PF>		GT 5.
								3−	3·	−	GT -3.
								4−	4·	−	GT -7.
								5−	5·	−	GT -12.
								*	-12·	* +	
									<PF>		GT -12.

Note 2: <PF> ....Paper feed

Key								Touch	Print			Display	
TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M						
								GT		−7·	* ◊	GT	−7.
								GT		−7·	* *		
									<PF>				−7.
F	4/5	OFF	Σ	OFF	CAL	OFF	OFF	MI+	––––––––1––––––––				
										−7·	M +	MI	−7.
								5				MI	5.
								MII+	––––––––2––––––––				
										5·	M +	MII	5.
												MI	
								MI◊	––––––––1––––––––				
										−7·	M ◊	MII	−7.
												MI	
								MI*	––––––––1––––––––				
										−7·	M *		
									<PF>			MII	−7.
								MII◊	––––––––2––––––––				
										5·	M ◊	MII	5.
								MII*	––––––––2––––––––				
										5·	M *		
									<PF>				5.
								#/P		5·	◊		5.
								2#/P	#2				2.
								#/P		2·	◊		2.
								0÷		0·	÷		0.
								=		0·	=		0.
									·················				
										0·	*		
									<PF>			E	0.
								C		0·	*		
									<PF>				0.
F	CUT	OFF	OFF	OFF	SETI	OFF	OFF		––––––––1––––––––				
										0·	%		
									<PF>				0.
								3					3.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF		––––––––1––––––––				
										3·	%		
									<PF>				0.
								C		0·	*		
									<PF>				0.
F	CUT	OFF	OFF	OFF	SETI	OFF	OFF		––––––––1––––––––				
										3·	%		
									<PF>				3.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF						0.
F	CUT	OFF	OFF	OFF	SETII	OFF	OFF		––––––––2––––––––				
										0·	%		

Note 2: <PF> ....Paper feed

Key									Print			Display
TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M	Touch				
									<PF>			0.
								5				5.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF		--------2--------			
									5·	%		
									<PF>			0.
F	CUT	OFF	OFF	OFF	SETII	OFF	OFF		--------2--------			
									5·	%		
									<PF>			5.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF					0.
								1560				1,560.
								+TAXI	--------1--------			
									1560·			
									46·8	◊		
									1606·8	*		
									<PF>			1,606.8
								1560				1,560.
								+TAXII	--------2--------			
									1560·			
									78·	◊		
									1638·	*		
									<PF>			1,638.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF	+TAXI	--------1--------			
									1638·	◊		
									49·14	◊		
									1687·14	*		
									<PF>			1,687.14
								1560				1,560.
								×	1560·	×		1,560.
								78900				78,900.
F	4/5	OFF	OFF	OFF	CAL	OFF	OFF	+TAXI	--------1--------			
									78900·	=		
									123084000·	◊		
									3692520·	◊		
									126776520·	*		
									<PF>			126,776,520.
								=				126,776,520.
								5				5.
								×	5·	×		5.
								+TAXI				5.
								=	5·	=		
									25·	*		
									<PF>			25.
								+TAXI	--------1--------			
									25·	◊		

Note 2:　<PF> ....Paper feed

Key									Print		Display
TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M	Touch			
									0·75 ◊		
									25·75 *		
									<PF>		25.75
								=			25.75
								C	0· *		
									<PF>		0.
2	CUT	OFF	OFF	OFF	CAL	OFF	OFF	1560			1,560.
								+	1560·00 +		1,560.00
								1100			1,100.
								+	1100·00 +		2,660.00
								+TAXII	--------2--------		
									2660·00 ◊		
									133·00 ◊		
									2793·00 *		
									<PF>		2,793.00
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF	+TAXI	--------1--------		
									2793·00 ◊		
									83·79 ◊		
									2876·79 *		
									<PF>		2,876.79
								98000000			
								00			9,800,000,000.
								+TAXI	--------1--------		
									9800000000·		
									294000000· ◊		
									....		
									1·009400000 *		
									<PF>		E 1.009400000
								C	0· C		
									<PF>		0.
								1560			1,560.
								+/−			−1,560.
								+TAXI	--------1--------		
									−1560·		
									−46·8 ◊		
									−1606·8 *		
									<PF>		−1,606.8
								1560			1,560.
								−TAXI	--------1--------		
									1560·		
									−45·436894 ◊		
									1514·563106 *		
									<PF>		1,514.563106
								−TAXI	--------1--------		

Note 2: <PF> ....Paper feed

TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M	Touch	Print	Display
									1514·563106 ◊	
									−44·113489 ◊	
									1470·449617 *	
									<PF>	1,470.449617
								1560		1,560.
								−TAXII	--------2--------	
									1560·	
									−74·285715 ◊	
									1485·714285 *	
									<PF>	1,485.714285
								−TAXII	--------2--------	
									1485·714285 ◊	
									−70·7483 ◊	
									1414·965985 *	
									<PF>	1,414.965985
F	CUT	OFF	OFF	OFF	SETI	OFF	OFF		--------1--------	
									3· %	
									<PF>	3.
								C		0.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF		--------1--------	
									0· %	
									<PF>	0.
F	CUT	OFF	OFF	OFF	SETI	OFF	OFF		--------1--------	
									0· %	
									<PF>	0.
								1234		1234.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF		--------1--------	
									1234· %	
									<PF>	0.
F	CUT	OFF	OFF	OFF	SETII	OFF	OFF		--------2--------	
									5· %	
									<PF>	5.
								C		0.
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF		--------2--------	
									0· %	
									<PF>	0.
								98000000 00		9,800,000,000.
								+TAXI	--------1--------	
F	CUT	OFF	OFF	OFF	CAL	OFF	OFF		9800000000·	
									·················	
									0· *	
									<PF>	E 0.
								C	0· *	

Note 2:   <PF> ....Paper feed

TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M	Touch	Print		Display
									<PF>		0.
								2			2.
								×	2·	×	2.
								3			3.
								×	3·	×	6.
								EXC	3·	#	3.
								×	6·	×	18.
								EXC	6·	#	6.
								×	18·	×	108.
								EXC	18·	#	18.
								×	108·	×	1,944.
								=	108·	=	
									209952·	*	
									<PF>		209,952.
								9			9.
								√	9·	√	
									3·	*	
									<PF>		3.
								√	3·	√	
									1·732050807	*	
									<PF>		1,732050807
								+/−			−1,732050807
								√	−1·732050807	√	
									....		
									−1·316074012	*	
									<PF>		E −1·316074012
								C	0·	*	
									<PF>		0.
A	CUT	OFF	OFF	OFF	CAL	OFF	OFF	123			123.
								+	1·23	+	1.23
								456			456.
								+	4·56	+	5.79
								◊	5·79	◊	5.79
								*	5·79	*	5.79
									<PF>		5.79
AII	CUT	OFF	OFF	OFF	CAL	OFF	OFF	789			789.
								×	789·	×	789.
								100			100.
								=	1·00	=	
									789·00	*	
									<PF>		789.00
(Don't do it.)								123			123.
								+	123·00	+	123.00
								456			456.

Note 2:   <PF> ....Paper feed

Key									Print	Display
TAB	4/5	IC	Σ	GT	MOD	2 TAX	2 M	Touch		
								+	456·00　　+	579.00
								*	579·00　　*	
									<PF>	579.00
F	4/5	OFF	OFF	OFF	CAL	ON	ON	(RESET)	<PF>	
									*	
									<PF>	0.
								7		7.
								+/−		−7.
								MI+	−7·　　M +	MI 　−7.
								5		MI 　5.
								MII+		MI 　5.
								MI◊	−7·　　M ◊	MI 　−7.
								MI*	−7·　　M *	
									<PF>	−7.
F	4/5	OFF	OFF	OFF	SETI	ON	ON		0·　　%	
									<PF>	0.
								3		3.
F	4/5	OFF	OFF	OFF	CAL	ON	ON		3·　　%	
									<PF>	0.
								C	0·　　*	
									<PF>	0.
F	4/5	OFF	OFF	OFF	SETI	ON	ON		3·　　%	
									<PF>	3.
F	4/5	OFF	OFF	OFF	CAL	ON	ON			0.
F	4/5	OFF	OFF	OFF	SETII	ON	ON			0.
								5		5.
F	4/5	OFF	OFF	OFF	CAL	ON	ON			5.
F	4/5	OFF	OFF	OFF	SETII	ON	ON			5.
F	4/5	OFF	OFF	OFF	CAL	ON	ON			5.
								CE		0.

Note 2:   <PF> ....Paper feed

Maximum Ratings (V$_{SS}$ = 0 V)

Characteristics	Symbol	Rating	Unit
Supply voltage 1	V$_{DD}$	−0.3~6	V
Supply voltage (LCD drive)	V$_{LC}$	−0.3~ V$_{DD}$ + 0.3	V
Input voltage	V$_{IN}$	−0.3~ V$_{DD}$ + 0.3	V
Output voltage	V$_{OUT}$	−0.3~ V$_{DD}$ + 0.3	V
Output current	I$_{OUT}$	3.2	mA
Power dissipation	P$_D$	600	mW
Soldering temperature	T$_{sld}$	260 (10 s)	°C
Storage temperature	T$_{stg}$	−55~125	°C
Operating temperature	T$_{opr}$	0~40	°C

Electrical Characteristics

Recommended Operating Conditions (V$_{SS}$ = 0 V, T$_{opr}$ = 0~40°C)

Characteristics	Symbol	Test Circuit	Test Condition	Min	Typ.	Max	Unit
Operating temperature	T$_{opr}$	—	—	0	—	40	°C
Supply voltage	V$_{DD}$	—	NORMAL	4.5	—	5.5	V
		—	SLOW				
		—	HOLD	2.0			
High-level input voltage (non-schmitt circuit)	V$_{IH1}$	—	V$_{DD}$ ≧ 4.5 V	V$_{DD}$ × 0.7	—	V$_{DD}$	V
High-level input voltage (schmitt circuit)	V$_{IH2}$			V$_{DD}$ × 0.75	—	V$_{DD}$	V
High-level input voltage	V$_{IH3}$	—	V$_{DD}$ < 4.5 V	V$_{DD}$ × 0.9	—	V$_{DD}$	V
Low-level input voltage (non-schmitt circuit)	V$_{IL1}$	—	V$_{DD}$ ≧ 4.5 V	0	—	V$_{DD}$ × 0.3	V
Low-level input voltage (schmitt circuit)	V$_{IL2}$			0	—	V$_{DD}$ × 0.25	V
Low-level input voltage	V$_{IL3}$	—	V$_{DD}$ < 4.5 V	0	—	V$_{DD}$ × 0.1	V

DC Electrical Characteristics ($V_{SS} = 0$ V, $T_{opr} = 0 \sim 40°C$)

Characteristics	Symbol	Test Circuit	Terminal	Test Condition	Min	Typ.	Max	Unit
Hysteresis voltage (schmitt circuit)	V_{HS}	—	Hysteresis input	—	—	0.7	—	V
Input current	I_{IN1}	—	KO port, TEST, $\overline{RESET}$, $\overline{HOLD}$	$V_{DD} = 5.5$ V $V_{IN} = 5.5/0$ V	—	—	±2	μA
	I_{IN2}	—	Open drain R port, P port					
Input resistance	R_{IN1}	—	KO port TEST with input resistor	$V_{DD} = 5.5$ V $V_{IN} = 5.5/0$ V	30	70	150	kΩ
	R_{IN2}	—	$\overline{RESET}$, $\overline{HOLD}$		100	220	450	
Output leakage current	I_{LO1}	—	Sink open drain R port	$V_{DD} = 5.5$ V $V_{OUT} = 5.5$ V	—	—	2	μA
	I_{LO2}		Source open drain R port, P port	$V_{DD} = 5.5$ V $V_{OUT} = -1.5$ V	—	—	−2	
High-level output voltage	V_{OH}	—	Source open drain R port, P port	$V_{DD} = 5.5$ V $I_{OH} = -1.6$ mA	2.4	—	—	V
Low-level output voltage	V_{OL}	—	Sink open drain R port	$V_{DD} = 5.5$ V $I_{OL} = 1.6$ mA	—	—	0.4	V
Pull-down resistance	R_{OUT}	—	R port, P port	$V_{DD} = 5.5$ V $V_{IN} = 5.5$ V	30	70	150	kΩ
Output resistance	R_{OS}	—	SEG	$V_{DD} = 5$ V $V_{DD} - V_{LC} = 3$ V	—	—	35	kΩ
	R_{OC}	—	COM		3.8	4.0	4.2	V
Output voltage	$V_{O2/3}$	—	SEG/COM		3.3	3.5	3.7	V
	$V_{O1/2}$				2.8	3.0	3.2	
	$V_{O1/3}$							
Supply current (normal)	I_{DD}	—	—	$V_{DD} = 5.5$ V, $V_{LC} = V_{SS}$ $f_c = 4$ MHz	—	3	6	mA
Supply current (hold)	I_{DDH}	—	—	$V_{DD} = 5.5$ V	—	0.5	10	μA

Note 3: Typ. values are guaranteed at $T_{opr} = 25°C$, $V_{DD} = 5$ V.

Note 4: I_{IN1}: Excepts a current through a internal pull up/down resistor.

Note 5: R_{OS}, R_{OC}: Shows on-resistor at level switching.

Note 6: $V_{O2/3}$: Shows 2/3 level output voltage at which 1/4 or 1/3 duty LCD drive.

Note 7: $V_{O1/2}$: Shows 1/2 level output voltage at which 1/2 duty or static LCD drive.

Note 8: $V_{O1/3}$: Shows 1/3 level output voltage at which 1/4 or 1/3 duty LCD drive.

Note 9: I_{DD}, I_{DDH}: Current consumption at $V_{IN} = 5.3$ V/0.2 V

           Should be under that KO port is open and R port Voltage level is valid.

Oscillation Circuit (V$_{SS}$ = 0 V, V$_{DD}$ = 4.5~5.5 V, T$_{opr}$ = 0~40°C)

Recommended Circuit	Test Condition	Min	Typ.	Max	Unit
XIN XOUT R C	V$_{DD}$ = 5.0 V C = 100 pF R = 1 kΩ ± 2%	2.4	4.0	5.6	MHz

AC Electrical Characteristics (V$_{SS}$ = 0 V, V$_{DD}$ = 4.5~5.5 V, T$_{opr}$ = 0~40°C)

Characteristics	Symbol	Test Circuit	Test Condition	Min	Typ.	Max	Unit
Instruction cycle time	t$_{CY}$	—	NORMAL	1.9	—	20	μs
		—	SLOW	235	—	267	
High-level clock pulse width	t$_{WCH}$	—	External clock operation	80	—	—	ns
Low-level clock pulse width	t$_{WCL}$	—			—		ns
Shift data hold time	t$_{SDH}$	—	—	0.5 tcy − 300	—	—	ns
High speed timer/counter input frequency	f$_{HT}$	—	—	—	—	f$_c$	MHz

Waveforms for Display

Pad Location Table

(μm)

Name	X Point	Y Point		Name	X Point	Y Point
KO0	−1282	−2074		SEG12	1202	2074
KO1	−1122	−2074		SEG13	1042	2074
KO2	−962	−2074		SEG14	881	2074
KO3	−802	−2074		SEG15	721	2074
R_{80}	−641	−2074		SEG16	561	2074
R_{81}	−438	−2074		SEG17	401	2074
R_{82}	−278	−2074		SEG18	241	2074
R_{83}	−74	−2074		SEG19	80	2074
V_{DD}	86	−2074		SEG20	−80	2074
R_{90}	246	−2074		SEG21	−240	2074
R_{91}	449	−2074		SEG22	−400	2074
R_{92}	610	−2074		SEG23	−560	2074
R_{40}	802	−2074		SEG24	−721	2074
R_{41}	962	−2074		SEG25	−881	2074
R_{42}	1122	−2074		SEG26	−1041	2074
R_{43}	1282	−2074		SEG27	−1201	2074
R_{50}	1644	−2011		SEG28	−1644	1961
R_{51}	1644	−1807		SEG29	−1644	1801
R_{52}	1644	−1647		SEG30	−1644	1641
R_{53}	1644	−1444		SEG31	−1644	1481
R_{60}	1644	−1283		COM1	−1644	1321
R_{61}	1644	−1080		COM2	−1644	1160
R_{62}	1644	−920		COM3	−1644	1000
R_{63}	1644	−716		COM4	−1644	840
R_{70}	1644	−556		V_{LC}	−1644	520
R_{71}	1644	−353		P10	−1644	359
R_{72}	1644	−193		P11	−1644	156
R_{73}	1644	62		P12	−1644	−4
SEG0	1644	223		P13	−1644	−208
SEG1	1644	383		V_{SS}	−1644	−368
SEG2	1644	543		P20	−1644	−528
SEG3	1644	703		P21	−1644	−731
SEG4	1644	863		P22	−1644	−892
SEG5	1644	1024		P23	−1644	−1095
SEG6	1644	1184		TEST	−1644	−1255
SEG7	1644	1344		XIN	−1644	−1415
SEG8	1644	1504		XOUT	−1644	−1651
SEG9	1644	1664		BRESET	−1644	−1811
SEG10	1644	1825		BHOLD	−1644	−1971
SEG11	1644	1985				

Chip Layout


```
Chip size       : 3.78 × 4.67 (mm)
Chip thickness  : 450 ± 30 (μm)
Substrate       : V_SS
Pad size        : 100 (μm□)
```

Pad Layout

Active Element

SCRIBE LINE

Pad pitch 160 (μm)

The Proposal of Outer Circuit for Tax Rate Holding with Back-Up Battery.

Note 10: V_1 = +3 V: Battery supply

   V_2 = +5 V: DC supply

$\left[\begin{array}{l}\overline{\text{HOLD}} \text{ pin is pulled down in the LSI, but normally pulled up to } V_{DD}. \\ \overline{\text{RESET}} \text{ pin is pulled up to } V_{DD}.\end{array}\right]$

(1)   Setting POWER SW to ON, V_2 is supplied to V_{DD} pin, and also to $\overline{\text{HOLD}}$ pin.
      Then calculator operates normally.

(2)   Setting POWER SW from ON to OFF, V_1 is supplied to V_{DD} pin and V_{SS} is supplied to $\overline{\text{HOLD}}$ pin.
      Under this connection, TAX RATE is held.

(3)   Setting POWER SW to ON, V_2 is supplied to V_{DD} pin, and also to $\overline{\text{HOLD}}$ pin.
      Then calculator operates normally with TAX RATE to be held.

Note 11: V_1 (battery) should be supplied to the circuit after V_2 (DC) supply, because of prevention from
         exhaustion of battery and abnormal operation.

RESTRICTIONS ON PRODUCT USE